

FIG. 1




FIG. 2
POU920000103US1
W.J. Rooney, et al.
Sheet 2/8




FIG. 3






FIG. 4



Compare Channel Components Command

FIG. 5



Response Block

FIG. 6




FIG. 7

250

252 254 256 258 260 262

Manufacturer	Device Type	Model No.	Cluster	I/O Bay	Interface Card
--------------	-------------	-----------	---------	---------	----------------

FIG. 8

300

308 310 312 302 304 306

Manufacturer	Device Type	Model No.	Cluster Mask	I/O Bay Mask	Interface Mask
IBM	3990	006	00F0	00FC	0000
IBM	3990	G03	00F0	00FC	0000
IBM	3990		00F0	00FC	0000
IBM	2105		0080	00E0	00FC
IBM			0080	00E0	00FC
ABC	3990	03	00F0	00FC	0000
			00F0	00FC	0000

324

328

330

FIG. 9a




FIG. 9b

